


Osteoporosis Femur

Price inquiry: +48 605999769, kontakt@openmedis.pl

Product code: MA02792



This model provides an impressive demonstration of the difference between a normal and osteoporotic femur. The osteoporotic bone shows a markedly damaged structure and bone fracture. The upper half of the femur is shown in each case. On baseboard, can be removed and disassembled. Original size natural casting.